

Overview	
PCN tracking number	#EU550230606a
Products Affected	iS7,S100,H100 LCD Keypad
Reason for change	Changes to increase keypad titles so that parameters can be increased when customizing the OS after memory is increased due to the new MCU
Projected mass production date	iS7/S100 Keypad: Keypads manufactured after June 5 th or after out of stock H100 Keypad: Keypads manufactured after June 12 th

Affected Products			
Item code	Description	Previous Version	New Version
11040002523	ASS'Y,LOADER(LCD),SV-IS7/LSLV-S100,NEW	V3.10a_D220919	V3.11a_D23.04.27
64110038	INV,LCD LOADER,SV-IS7(NEW PI)	V3.10a_D220919	V3.11a_D23.04.27
11040002604	ASS'Y,LOADER(LCD),LSLV-H100	S2.00_D22.01.12_T2_P1	S2.01_D22.07.10_T2_P1
64160057	INV,OPTION(H100 LCD LOADER),LCEN-H100	S2.00_D22.01.12_T2_P1	S2.01_D22.07.10_T2_P1
11040003601	ASS'Y,LOADER(LCD),LSLV-H100(Eng/Kor)	S91.22_D22.01.14_T2_P1	S91.23_D23.04.06
64160010	INV,LCD LOADER(Korean),LSLV-H100	S91.22_D22.01.14_T2_P1	S91.23_D23.04.06

Description of Change
iS7/S100 Standard Keypad Software: V3.10a_D220919 -> V3.11a_D23.04.27 H100 Standard Keypad Software: S2.00_D22.01.12_T2_P1 → S2.01_D22.07.10_T2_P1 H100 Korean Keypad Software: S91.22_D22.01.14_T2_P1 → S91.23_D23.04.06_T2_P1
- The number of Keypad titles has been increased. - There's no parameter changes so that there is no compatible issue.